



www.wayne-dalton.com

idrive[®]

for Torquemaster[®] Springs

Update Revision Label

IMPORTANT!

You **MUST** replace revision label when upgrading the MCB (Motor Control Board) of the TorqueMaster[®] idrive[®] opener.

