

Operator Bracket (Supplied By Others)

For Models: 8300, 8500, 5150, 5200

Supplemental Insert

This supplemental installation instruction is to be used as a supplement to the main Installation Instruction and Owner's Manual provided with the door. The instructions included in this document are only those which deviate from the standard installation. All warnings and cautions listed in the main manual are applicable to this supplemental instruction as well.

www.wayne-dalton.com

Installation Instructions

⚠ WARNING

POTENTIAL DAMAGE TO YOUR TOP SECTION MAY OCCUR IF INSTALLER DOES NOT FOLLOW THESE OPERATOR BRACKET (SUPPLIED BY OTHERS) INSTRUCTIONS CLOSELY. IF THE INSIDE PORTION OF YOUR TOP SECTION HAS PINSTRIPES, IT IS VERY IMPORTANT TO POSITION AND INSTALL THE OPERATOR BRACKET (SUPPLIED BY OTHERS) LOCATED ON THE TOP SECTION, AS SHOWN. THIS WILL ENSURE THE OPERATOR BRACKET FASTENERS (SUPPLIED BY OTHERS) BEING USED ARE GOING THROUGH THE BACKUP PLATE INSIDE THE TOP SECTION. IT IS EQUALLY IMPORTANT FOR THE INSTALLER TO NEVER INSTALL THE OPERATOR BRACKET UPSIDE DOWN. NOT FOLLOWING THESE INSTRUCTIONS CAN RESULT IN OPERATOR BRACKET BEING PULLED OFF THE TOP SECTION.

